

# One-mm 3D Laser Imaging Survey for Comprehensive Runway Evaluation

---


**Joshua Q. Li, Kelvin C. P. Wang, Guangwei  
Yang, and Lin Li**

**Oklahoma State University**

**2014 FAA Worldwide Airport Technology  
Transfer Conference**



# Full Size Runway 16-34





# Full Size Runway 16-34



# Evaluation Objectives

---

- ❑ PaveVision3D Ultra imaging of runway and taxiways at 1mm resolution
- ❑ PCI analysis
- ❑ Longitudinal profiling
  - Boeing Bump Index (BBI)
- ❑ Runway groove identification, measurement, evaluation
- ❑ Transverse profiling






# PaveVision3D Ultra Systems



# 3D Ultra Data Collection System






# Data Collection Techniques






# Data Collection Summary




# 3D Ultra Data

---



# 3D Ultra Data

---





# Runway Surface Examination

---

- ❑ Reference Station 6000ft to the intersection of runway and taxiway F
- ❑ 61 runs of transverse 1mm 3D Ultra data (953 frames)
- ❑ Analysis tool: MHIS-3D
- ❑ Key surface defects
  - Surface irregularity
  - Patching
  - Popouts
  - Scaling
  - Joint spalling
  - Excessive grinding
  - Faulting
  - Grooving problems



# Surface Evaluation Results


---

Surface Defect	Total % of Frames
Surface Irregularity	30.64
Popouts	42.60
Joint Spalling	16.78
Faulting	10.08
Patching	6.08
Scaling	11.96
Excessive Grinding	12.69
Missing Grooves	1.36





# Airport PCI Analysis

- ❑ PCI – Pavement Condition Index
- ❑ Quantitative Measure of Pavement Condition
- ❑ FAA AC 150/5380-6A (ASTM D5340-03)
- ❑ Pavement distress
  - Type
  - Quantity
  - Severity







# MHIS-Airport2D: Stitching



# MHIS-Airport2D: PCI Analysis



# MHIS-Airport3D Interface





# PCI Results


Location		PCI
Runway Overall		91
Runway Segment	Taxiway K-C	92
	Taxiway C-E	89.3
	Taxiway E-F	92.8
	Taxiway F-A	90.7

- ❑ PCI: excellent condition
- ❑ MHIS-Airport: only 2D capability
- ❑ Many surface issues: not in PCI procedure
  - Surface irregularity
  - Groove problems
  - Surface grinding
  - Construction problems



# Runway Longitudinal Profiling


- Boeing Bump Methodology
  - FAA AC 150/5380-9



**BBI = (measured bump height) / (limit of acceptable bump height)**




# Example Longitudinal Profile




- Runway length: 8795 ft (8800ft designed)
- Elevation difference: 22.7ft (23 ft designed)



# Runway Boeing Bumps




# Taxiway Boeing Bumps






# Runway BBI Results




# Taxiway BBI Results



# Runway Groove Evaluation



## □ Standard Rectangle Groove (AC 150/5320-12C)



## □ Groove Tolerance



Groove type	Recommended configuration (Unit: in)		Tolerance (Unit: in)		Acceptable range			
			Lower limit	Upper limit	Unit: inch		Unit: mm	
Rectangular	Depth	1/4	-1/16	1/16	0.19	0.31	4.76	7.94
	Width	1/4	0	1/16	0.25	0.31	6.35	7.94
	Spacing	1 1/2	-1/8	0	1.38	1.5	34.9	38.1

# LS-40 Data – Grinded Surface








# LS-40 Data – Grinded Surface



# LS-40 Data – Uneven Surface




# Grooving Software







# Groove Evaluation (Slab 4 Runs 7&8)



(a) Groove Depth




(b) Groove Width



(c) Groove Spacing




# Groove/Joint Evaluation




# Transverse Profiling & Cross Slope

- ❑ Cross Slope Calculation
  - AASHTO method
  - TxDOT method
  - Linear regression method
- ❑ Transverse Grade – Category C & D Airports (FAA Guidance)








# Example Cross Slope (West-Half)



# Runway Cross Slope



# Cross Slope Evaluation



# Conclusions

---

- ❑ PaveVision3D Ultra
  - Able to collect 1mm surface data at 60mph for comprehensive airport runway evaluation
- ❑ Runway PCI: Excellent
  - Many construction related distresses not in PCI definitions
- ❑ Acceptable BBI
  - After runway surface grinding
- ❑ Substantial construction quality issues
  - Slab unevenness, Joint problems, Pop outs, Out-of-spec grooves, Variations of cross slope





# Thank You!

---

**Kelvin C. P. Wang**

**School of Civil and Environmental Engineering**

**Oklahoma State University**

**405-744-6328**

**[kelvin.wang@okstate.edu](mailto:kelvin.wang@okstate.edu)**

